






M60EX014



EN Assembling scheme
 DE Aufbauanleitung
 FR Schéma d'assemblage





1		M48A0189	x8	2		M48A0031	x8
4		3.5x17 M42A0017	x16	3		M48A0133	x8
5		M4x22 M42C0009	x4	6		M45F4001	x2
7		M45F9009	x2	8		3.0x15 P M42A0004	x4
9		M45F9009	x2	10		3.0x15 K M42A0003	x4




1




2



3





1)




2


2)




4




1)




2)




3)




5




1)





2)








3)







6



7



8







M60EX065

1/1




Reikalingi įrankiai:

Инструменты для сборки:


Requiring tools:




Surinkimo schema
Схема сборки
Assembling scheme




U2N100/U2C100
H=754



U3N100/U23100
H=1120



U4N100/U4C100
H=1508



U5N100/U5C100
H=1874